CENTRAL SACRAMENTO AREA Fact Sheet Site 69.9

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento River

River Mile: 69.9 Latitude/Longitude:

38.667460/-121.620240

Nearest Impact Area:

West Sacramento/Woodland

County: Yolo Bank: Right

Type of Damage

Bank erosion

Length of Repair

1,600 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources

For further information, please contact:

Elizabeth Scott DWR Public Affairs Office (916) 835-5344 leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

